


OPEL CORSA AE215 7304958.1./2.xxx		10	description : Repair solution cover	sc/cc/ cc[A]
AFO	Benennung / Teile-Nr.	POS. QM Plan	Arbeitsgang :	Merk mal

10		
20 	2St. Brackets assembly ,see photo .: 011619 004 <u>Danger: do not scratch!</u>	
30	  Psition the brackets Position Y = 25mm Position X = 40mm	

Revision: 001	Erstellt: K.Schumayer	Datum:	geändert: K.Schumayer	Datum:
------------------	--------------------------	--------	--------------------------	--------

OPEL CORSA AE215 7304958.1./2.xxx		10	description : Repair solution cover	sc/cc/ cc[A]
AFO	Benennung / Teile-Nr.	POS. QM Plan	Arbeitsgang :	Merk mal

30		 Position the brackets Door side position X = 30mm	
40		Tool for assembly scraper Press with scraper	
50 		for assembly scraper press in Danger: do not scratch!	

Revision: 001	Erstellt: K.Schumayer	Datum:	geändert: K.Schumayer	Datum:
------------------	--------------------------	--------	--------------------------	--------

OPEL CORSA AE215 7304958.1./2.xxx		10	description : Repair solution cover	sc/cc/ cc[A]
AFO	Benennung / Teile-Nr.	POS. QM Plan	Arbeitsgang :	Merk mal

60		Tool for assembly Plastic hammer with cloth	
70		With plastics hammer strike in chanel Danger: do not scratch!	
110 	Visually check the cover		

Revision: 001	Erstellt: K.Schumayer	Datum:	geändert: K.Schumayer	Datum:
------------------	--------------------------	--------	--------------------------	--------